## LOS RIOS COMMUNITY COLLEGE DISTRICT

PURCHASING: (916) 568-3071 • FAX: (916) 568-3145 ACCOUNTING OPS: (916) 568-3065 • FAX: (916) 286-3636

PLEASE SEE REVERSE SIDE FOR TERMS AND CONDITIONS.

Supplier: 0000018171 PAPE MATERIAL HANDLING PO BOX 35144 # 5077 SEATTLE WA 98124-5144

email:

Date	Revision	Page	
04/25/201	.9	1	
Payment To	erms Freight Terms	Ship Via	
NET 30	Shipping Point	Best Metho	
Reference:		Location / Dept	
1018659 TURNERD HANEYB		04OPER	

Ship To:

FOLSOM LAKE COLLEGE

RECEIVING

10 COLLEGE PARKWAY FOLSOM CA 95630 **United States** 

Bill To:

1919 Spanos Court

Sacramento CA 95825-3981

**United States** 

Tax Exempt? N

Line-Sch	Item/Description	Quantity UOM	PO Price	Extended Amt	Due Date
1- 1	LABOR SERVICE AND DIAGNOSTIC ON SCISSOR LIFT - AWP36S (9505) (PLEASE SEE ATTACHED INVOICE FOR SPECS)	1.00EA	2,700.00	2,700.00	04/17/2019
2- 1	TRANSPORTATION FEE	1.00EA	218.75	218.75	04/17/2019

PAY INVOICE WO# 11827180 - WORK HAS BEEN COMPLETED

MAKE/MODEL- GENIE AWP36S SERIAL #AWP36S35376

> Sub Total Amount Sales Tax Amount **Total PO Amount**

2,918.	75
0.	00
2,918.	75
	2,918. 0. 2,918.

GENFD

1.1

FL.VA.OPER

65100 00000

<u>Proj</u> 041A

<u>Amount</u> 2.918.75 **BYear** 2019

0001018659CHAVEZA17-APR-2019

Verification of this purchase order can be made using the Los Rios Community College District web site listed below. If you have any questions, please contact the Purchasing Office at (916)568-3071.

http://www.losrios.edu/purchasing/povalidation

All shipments, invoices, and correspondence must be identified with our Purchase Order Number. Overshipments will not be accepted unless authorized by Buyer prior to shipment.

**Authorized Signature** 

Notice to vendor: You are responsible for delivering goods and delivery documents to the Receiving Department at the site. Failure to do so will delay payment processing. Vendor is responsible for obtaining verification of delivery by authorized Receiving Room personnel. Receipt of goods by other parties and failure to obtain authorized signatures may also delay payment. NOTE: PAYMENT TERMS NET 30 MATERIAL SAFETY DATA SHEETS (MSDS) must be provided with the delivery of product as required by law.

## Requisition

Supplier: PAPE MATERIAL HANDLING

PO BOX 35144 # 5077 SEATTLE WA 98124-5144

**United States** 

email:

Ship To:

RECEIVING

10 COLLEGE PARKWAY FOLSOM CA 95630-6798 0000018171

Business Unit: GENFD **OPEN** Req ID: Date

0001018659 04/16/2019

Requisition Name:

PAPE MATERIAL HANDLING

Requester

Debbie Turner

Requester Signature

Buyer: Brenda Haney

Approved:

Entered By: CHADWICS 16-APR-2019

Line-Schd	Description	Quantity UOM		Price	Extended Amt Due Date	
1-1	LABOR SERVICE AND DIAGNOSTIC ON SCISSOR LIFT - AWP36S (9505) (PLEASE SEE ATTACHED INVOICE FOR SPECS)	1	EA	2,700.00	2,700.00 04/16/2019	
2-1	TRANSPORTATION FEE	1	EA	218.75	218.75 04/16/2019	

2,918.75 Sub-total 0.00 Est. tax

Page

Total Requisition Amount:

2,918.75

PLEASE PAY PER ATTACHED INVOICE WORK ORDER - 11827180

MAKE/MODE - GE AWP36S SERIAL #AWP36S35376

**设施** CONTROL OF SECTION U

Acct Fd 5600 11 BU <u>Sub</u> <u>Proj</u> Prog <u>Amount</u> GENFD FL.VA.OPER 65100 00000 041A 2,918.75 04/09/19 PAPE ' MATERIAL HANDLING \* W.O.# 11827180 13:29:32 BRANCH- 11 PAGE- 01 FINAL PREVIEW DIVISN- 04 WORK ORDER- 11827180 TRUCK NUM-SOLD TO: 5226506 SHIP TO: PO#: V-18057B FOLSOM LAKE COLLEGE -7.1.17 THRU 6.30.18 HARRIS CTR FOR THE ARTS SEE AUTH NAMES IN FILE 10 COLLEGE PARKWAY 00000 **FOLSOM** CA 95630 PHONE • 916-608-6810 P.O. #- \*\* REQ \*\* DATE OPENED- 1/17/19 MAKE/MODEL · GE AWP36S EQUIP, NUMBER-SALE TYPE · 2 CHARGE SERIAL NUMBER. AWP36S35376 METER-SHOP/FLD/RES- S ord extension b-o ship --date----hrs-mech-S/F/R/Q·S JC· 0/ 0 LC·10 PC·10 NETTING PARTS SEGMENT 001 STUCK UP IN THE AIR 916-608-6580 \*\*\*COMING TO SHOP 1-28) CHECK FOR CAUSE OF PROBLEMS.... \*\* PER EMIL 3-20-19 CUSTOMER WANTS TO SCRAP THIS UNIT\*\*\*\* REPAIR PLATFORM BASKET. LOCATED TRUCK, VERIFIED COMPLAINT, FOUND BASKET STUCK AT FULL EXTENSION, FOUND BASKET CHAINS BINDING ON LOWER. BROUGHT IN ANOTHER TECH FOR ASSISTANCE, CUSTOMER SUPPLIED A BOOM LIFT, MANUALLY LOWERED BASKET, INFORMED CUSTOMER THAT UNIT IS UNSAFE TO USE, SENT INFO FOR PICKUP BROGHT LIFT IN TO THE SHOP. REMOVE THE PLATFORM. FOUND METAL AT THIS BASE OF THE LIFDT CYLINDER, TWO OF THE SEQUENCING CABLES WERE OUT OF ADJUSTMENT AND STRETCHED BEYOND USE. REMOVE THE UPRIGHT TO GET ACCESS TO THE LIFT CYLINDER. REMOVE THE BASE AND PULL THE CYLINDER. FOUND THAT THE LIFT CYLINDER ROD END TUBE HAS BEEN BENT AND IS SCRAPIUNG THE 2 CHANNEL. WILL NEED TO DISASSEMBLE THE UPRIGHT TO REPLACE THE 2ND CHANNEL COMPLETE AND TURN IN REPAIR QUOTE \* CUSTOMER DECLINED ALL REPAIRS AT THIS TIME. \* CUSTOMER WANTS TO SCRAP THE UNIT AT THIS TIME \* TRANSPORTATION 218.75 218.75 . 1 **PARTS** LABOR' SPEC SERVICES 218.75 TIME/MATERIALS 2,918,75 .00 2,700.00 SEGMENT TOTAL --> 2,918.75 218.75 BILLED TIME/MAT 2,918.75 .00 2,700.00 INVOICE TOTAL--> 2.918.75

> Per W.O. # 11827180 -Labor \$ 2700,00 Transpertation \$ 218,75

service & Diagnostic on scissor lift AWP365 (#9505)