#### PURCHASE ORDER NO 0001109219 LOS RIOS COMMUNITY COLLEGE DISTRICT

PURCHASING: (916) 568-3071 • FAX: (916) 568-3145 ACCOUNTING OPS: (916) 568-3065 • FAX: (916) 286-3636

PLEASE SEE REVERSE SIDE FOR TERMS AND CONDITIONS.

	1023196 TI	HIESSENL HANEYB	040PER
Supplier: 0000029448 STEAM CLEANERS INC 1115 E WATERLOO RD STOCKTON CA 95208	Ship To:	FOLSOM LAKE COLL RECEIVING 10 COLLEGE PARKW FOLSOM CA 95630-67	AY
Phone: (209) 943-0547 Fax: (209) 943-0548		United States	
email:	Bill To:	1919 Spanos Court Sacramento CA 95825 United States	-3981

Date

NET 30

Reference:

11/06/2019 Payment Terms

Tax Exempt? N					
Line-Sch	Item/Description	Quantity UOM	PO Price	Extended Amt	Due Date
1-1	H-GX390ES - GX390 HONDA ENGINE, 13 HP, ELECTRIC START	1.00EA	1,100.00	1,100.00	11/10/2019
2-1	LABOR	1.00EA	250.00	250.00	11/06/2019

ESTIMATE# 6019 10-29-2019

REPAIR WILL BE COMPLETED AT VENDOR SHOP.

Paid Ch# 94-787776 11/14/19 Amt \$ 1446.25

Sub Total Amount Sales Tax Amount Total PO Amount

Revision

Freight Terms

Shipping Point

Page

Location / Dept

Ship Via See Details

1,350.00
96.25
1,446,25

<u>BU</u>	<u>Acct</u>	<u>Fd</u>	Org	Prog	<u>Sub</u>	Proj	Amount	<u>BYear</u>
GENFD	5600	11	FL.VA.CUST	68300	00000	061E	1,446.25	2020

0001023196CHAVEZA31-OCT-2019

Verification of this purchase order can be made using the Los Rios Community College District web site listed below. If you have any questions, please contact the Purchasing Office at (916)568-3071.

http://www.losrios.edu/purchasing/povalidation

All shipments, invoices, and correspondence must be identified with our Purchase Order Number. Overshipments will not be accepted unless authorized by Buyer prior to shipment.

Authorized Signature	
R	
$\square$	

Notice to vendor: You are responsible for delivering goods and delivery documents to the Receiving Department at the site. Failure to do so will delay payment processing. Vendor is responsible for obtaining verification of delivery by authorized Receiving Room personnel. Receipt of goods by other parties and failure to obtain authorized signatures may also delay payment. NOTE: PAYMENT TERMS NET 30 MATERIAL SAFETY DATA SHEETS (MSDS) must be provided with the delivery of product as required by law.

### Requisition

Supplier:	STEAM CLEANERS INC 0000029448 1115 E WATERLOO RD STOCKTON CA 95208 United States	48 Business Unit: GENFD OPEN Req ID: Date Page 0001023196 10/28/2019 1 Requisition Name: STEAM CLEANERS INC.		
	Phone: (209) 943-0547 Fax: (209) 943-0548 email:	Requester Levi Thiessen		
Ship To:	hip To: 3753 BRADVIEW DRIVE SACRAMENTO CA 95827 Buyer: Brenda Haney Approved: Entered By: CHADWICS 28-0			
Line-Schd	Description	Quantity UOM Price Extended Amt Due Date		
1-1	H-GX390ES - GX390 HONDA ENGINE, 13 HP, ELECTRIC START	1 EA 1,100.00 1,100.00 10/28/2019		
2-1	TAX @ 8.75% FOR SUPPLY NEEDED	1 EA 96.25 96.25 10/28/2019		
3-1	LABOR	1 EA 250.00 250.00 10/28/2019		

1,446.25 Sub-total 0.00 Est. tax

Total Requisition Amount:

1,446.25

ESTIMATE #6019 DTD 10/29/2019

REPAIR WILL BE COMPLETED AT VENDOR SHOP.

<u>BU</u>	Acct	<u>Fd</u>	Org	Prog	Sub	<u>Proj</u>	Amount
GENFD	5600	11	FL.VA.CUST	68300	00000	061E	1,446.25

Approval Signature	Approval Signature	Approval Signature

#### J & S EQUIPMENT 1630 Challenge Drive, #120 Concord, CA 94520 925-686-0471

# STEAM CLEANERS INC.1115 E. Waterloo Road960 Arden WayStockton, CA 95205Sacramento, CA 95815209-943-0547916-442-1118

**Estimate** 

### Mailing address: PO Box 6803 Concord, CA 94524

Ship To	Date	Estimate #
FOLSOM LAKE COLLEGE LEVI THEISSEN 10 COLLEGE PARKWAY FOLSOM, CA 95630	10/29/2019	6019

P.O. No.

Qty	Item	Description	Cost	Total
	1 H-GX390ES 2.5 LABOR- SACRA	GX390 HONDA ENGINE, 13 HP, ELECTRIC START LABOR	1,100.00 100.00	1,100.00T 250.00
		PRESSURE PRO HOT WATER PRESSURE WASHER, S/N 07-03146 - ENGINE WILL NOT START, NO HEAT, GENERAL SERVICE		
		ATTEMPTED TO START MOTOR WITH ELEC START, COULD NOT, FOUND STARTER ROPE WAS BROKEN, REMOVED AND REPLACED STARTER ROPE AND ATTEMPTED TO START THE ENGINE, ENGINE IS LOCKED UP AND WILL ROTATE. REMOVED SPARK PLUG TO CHECK TO SEE IF IT HYDROLOCKED, IT WAS NOT. REMOVED HIGH PRESSURE PUMP FROM ENGINE SHAFT TO DETERMINE IF PUMP HAD ANYTHING TO DO WITH ENGINE LOCK UP, IT DID NOT. SPOKE WITH HONDA TECHNICAL SUPPORT, RECOMMENDED REMOVING BACK COVER OF ENGINE AND INSPECT THE CONDITION OF THE ROD, IT IS IN GOOD SHAPE. AGAIN SPOKE WITH HONDA TECH SUPPORT; THEY HAD ME CHECK THE ENGINE'S CAMSHAFT, VALVES, BALANCE GEAR AND PISTON RODS. ALL PARTS VISUALLY LOOK GOOD, SPOKE WITH HONDA SUPPORT AGAIN, THEIR AND OUR RECOMMENDATION IS REPLACE ENGINE AS IT CANNOT BE REPAIRED		
		OR THE COST OF REPAIRING IT WOULD FAR		
		Subto	tal	
		Sales	Tax (8.75%)	

## Total

#### J & S EQUIPMENT 1630 Challenge Drive, #120 Concord, CA 94520 925-686-0471

# STEAM CLEANERS INC.1115 E. Waterloo Road960 Arden WayStockton, CA 95205Sacramento, CA 95815209-943-0547916-442-1118

**Estimate** 

### Mailing address: PO Box 6803 Concord, CA 94524

Ship To	Date	Estimate #
FOLSOM LAKE COLLEGE LEVI THEISSEN 10 COLLEGE PARKWAY FOLSOM, CA 95630	10/29/2019	6019
		P.O. No.

Qty	Item	Description	Cost	Total
		EXCEED THE PRICE TO REPLACE IT.		
		REMOVE AND REPLACE HONDA GX390 ENGINE WITH NEW, TEST RUN UNIT FOR PRESSURE AND HEAT AND PERFORM GENERAL SERVICE ON UNIT. BECAUSE WE CANNOT TEST ANY OTHER COMPONENT OR SYSTEM UNTIL ENGINE IS REPLACED, WE WILL PROVIDE A SECOND REPAIR QUOTE IF NECESSARY AFTER WE HAVE TEST RUN UNIT.		

Subtotal	\$1,350.00
Sales Tax (8.75%)	\$96.25
Total	\$1,446.25